

# Environmental and Social Monitoring Third Report

Project Number: 48368-001  
July 2018

## MYA: Myingyan Natural Gas Power Project Part 3

Prepared by Environ Myanmar Co Ltd.

The environment and social monitoring report is a document of the borrower. The views expressed herein do not necessarily represent those of ADB's Board of Directors, Management, or staff, and may be preliminary in nature. Your attention is directed to the "Terms of Use" section of this website.

In preparing any country program or strategy, financing any project, or by making any designation of or reference to a particular territory or geographic area in this document, the Asian Development Bank does not intend to make any judgments as to the legal or other status of any territory or area.

**APPENDIX 5 – UPDATED GRIEVANCE MECHANISM DATABASE (31  
DECEMBER 2017)**

ID No.	Explain occurrence of grievance	Name of Complainant	Address (Filled in if details are)	Describe Grievance	Date of Grievance Occurred	Action Taken	Outcome
1	Villager worry for water discharge to Ayawaddy River and if they can't grow plants at the land after the construction.	-	Sate Nyan Village	Villager worry for water discharge to Ayawaddy River and if they can't grow plants at the land after the construction.	20170513	CRO Visited to GAD to find out the person who send the letter to explain him, but GAD can not find out as the letter do not mentioned name of sender. GAD recorded the case and replied to CRO that he will contact when he found the person.	GAD recorded that Sembcorp tried to explain to whom send the letter to grievance box
2	Villager worry for water discharge to Ayawaddy River and if they can't grow plants at the land after the construction.	-	Sate Nyan Village	Villager worry for water discharge to Ayawaddy River and if they can't grow plants at the land after the construction.	20170513	CRO Visited to GAD to find out the person who send the letter to explain him, but GAD can not find out as the letter do not mentioned name of sender. GAD recorded the case and replied to CRO that he will contact when he found the person.	GAD recorded that Sembcorp tried to explain to whom send the letter to grievance box
3	Family Misunderstanding of land issues. Land Compensation by EPGE has been carried out. The old lady who reported the grievance complained on EPC touching her land. Her family members did not communicate with her that the land has been compensated by EPGE and now the land title has been transferred to Daw Gyan Tin, Sarkhaar Village.	Daw Khin San	Aye Village	Notice board displayed " For this land, without any negotiation, so stop work. If want continue the work, negotiate with Daw Khin San and submit the letter from GAD"	20170607	EPGE Kyaw Min Htun and CRO met with Hta Naung Tai GAD, GAD discussed by phone to villager Daw Khin San.	After GAD explain to Daw Khin San, she understand the way to solve their family problem via by Government Land department and removed the notice board at the same day.
4	The letter sender (Daw Gyan Tin, Sarkhaar Village) want the land compensation as the cable (tower 5 to 6) is crossing above her firm. Another issue is the worker (JEM) chopped her tree and she wants compensate for it.	Daw Gyan Tin	Sar Khaar Village	The letter sender (Daw Gyan Tin, Sarkhaar Village) want the land compensation as the cable (tower 5 to 6) is crossing above her firm. One of her wild tree has chopped (as the cable array can be affected by the tree) and she want the compensation for it.	20170627	CRO, Kyaw Min Tun (EPGE), Aung Myo Kyaw JEM go down to Sarkhaar village head and see Daw Gyan Tin (LU on 20170627). EPGE said he will send the letter of this issue to Government to take necessary action and will reply when Government instruct him.	Villager understand and accept to wait EPGE (Government)'s reply as this kind of case can be handle by Government only. Sembcorp will only get updates and Ensure that EPGE has closed this case in the Future. Sembcorp has no position to settle this case. Case is managed and to be closed by EPGE (Government)
5	The letter sender (Ko Win Kyaing, Phat Taw Village) wants to be an employee of Sembcorp	Ko Win Kyaing	Phat Taw Village	The letter sender (Ko Win Kyaing, Phat Taw Village) applied for security position at Sembcorp and he requested by the letter to employ him.	20170615	CRO call by phone (Number provide our staff Zin Mar who from Phat Taw village), but the villager do not pick up the call and switch off. (20170627 not pickup, 20170701 switch off, 20170703 Switch off, 20170706 switch off). CRO talked with Village Head via telephone (13/07/2017) and explained about the Sembcorp Employment procedure that if someone wants to apply for a position, he/she need to submit the CV via Labour office.	Village Head understand and accepted Sembcorp employment procedure. He said he will explain to villager if there anyone wants to apply for the job at Sembcorp.
6	The letter sender (Ko Nay Lin, Hnan Village) wants Sembcorp to clean his firm and expend the water pound.	Ko Nay Lin	Hnan Village	Due to tower construction and irrection, his land need to leveling, cleaning and water pound expending. So, Ko Nay Lin wants Sembcorp to make as soon as possible.	20170619	Sembcorp (SDCI) fulfill all the fact he needed. leveling, expending the water pound and strip (29-30 June 2017 2 days)	Villager happy and his land is ready to plant. The water pound is expended.
7	The letter sender (Ko Kyaw Min Oo JEM Staff) suggested Project Management to increase enforcement on traffic related safety such Car & Motorbike movement especially during raining season and safety behavior of individual.	Ko Kyaw Min Oo	JEM	The letter say that "I wish Sembcorp Myingyan Power Company and Contractors more success. I wanted to say thank you Project Management and safety team who really taking care of workers safety and protect them to out of danger. However some employees need to improve on individual safety behaviour especially driving cars and riding motorbike in our site during raining. So I would like to suggest Project Managing to increase enforcement on unsafe practice personnel. Daily toolbox meeting highlighting about safe work practices however I have seen some worker still not follow site safety rule and regulation. But I understand that the safety team can't be taking care each individual safety. So if we followed project safety rule and regulation no one get hurt & our family will be happy. I pray for the Project Company together with safety team to complete the project safely."	20170731	-We (PMT & EPCs) made small campaign to promote existing traffic safety management and Behavioral base safety intervention.	-promoted existing traffic safety management and Behavioral base safety intervention.
8	Land owner U Phyu wants his firm land leveling and repair the boundary	U Phyu	Hnan Village	Land owner U Phyu wants his firm land leveling and repair the boundary	20170731	CPP (Sub-contractor of Sembcorp) trimmed the firming ground and repaired the boundaries according to the land owner's desire	Firm owner U Phyu happy and his land is ready to plant and cleaned.
9	Land owner U Thein Htun called CRO on 09-08-2017 and asked support for his firm land leveling.	U Thein Htun	Aye Village	Land owner U Thein Htun wants his firm land leveling.	20170809	CPP (Sub-contractor of Sembcorp) trimmed the firming ground and repaired the boundaries according to the land owner's desire	Firm owner U Thein Htun happy and his land is ready to plant and cleaned.
10	Land owner U Aung Naing Min requested support for his firm land leveling.	U Aung Naing Min	Hta Naung Tai	Land owner U Aung Naing Min wants his firm land leveling.	20170815	CPP (Sub-contractor of Sembcorp) trimmed the firming ground and repaired the boundaries according to the land owner's desire	Firm owner U Aung Naing Min happy and his land is ready to plant and cleaned.
11	Land owner U Aung Shwe requested support for his firm land leveling.	U Aung Shwe	Hta Naung Tai	Land owner U Aung Shwe wants his firm land leveling.	20170815	CPP (Sub-contractor of Sembcorp) trimmed the firming ground and repaired the boundaries according to the land owner's desire	Firm owner U Aung Shwe happy and his land is ready to plant and cleaned.
12	Myingyan GAD Officer given out the letter and pass to CRO via Sarkhaar village head and describe that, they found Sembcorp's sub-contractor's are using Sarkhaar road with over weight heavy truck for transportation and remind to Sembcorp to control the sub-contractors not to use for transportation with heavy truck.	U Nyi Nyi Aung Myingyan GAD Officer	Myingyan GAD Office	Myingyan GAD Officer given out the letter and pass to CRO via Sarkhaar village head and describe that, they found Sembcorp's sub-contractor's are using Sarkhaar road with over weight heavy truck for transportation and remind to Sembcorp to control the sub-contractors not to use for transportation with heavy truck.	20170814	PCO issued written final warning letter stated only use designated route for material transportation. CRO met with Myingyan GAD Officer, explained and submitted ESMP (Traffic Management plan).	GAD officer accepted on Sembcorp's ESMP (Traffic Management Plan).
13	Received email from Chan Thar (Engineer, SDCI) and described that "Land owner U Win Maung at zone-7, P-321(DT), he don't want to accept our stay footing & stay wire installation. So he come to site and barracked to install stay footing and wire of 4 nos. Please help to settle."	U Win Maung	Aye Village	Land owner don't wants to accept 4 stay wire in his land	20170817	Met with U Win Maung to for negotiation on - 17-08-2017, 24-08-2017, 30-08-2017, 05-09-2017, 06-08-2017 Participated in discussion by Land Owner, U Than Htun Aung (EPGE), ALO, CRO, Tint Khaing (MTKK).	Land owner agreed with 4 pole stay design and compensation MMK100,000. The compensation will be made after 4 stay design installation. Compensation done on 20171121
14	Sub contractor worker (JEM) write a letter via Plant Office Grievance Box and the letter means as comment:	Min Zaw Htoo JEM General Worker	JEM Company	As attached / Comment box	20171005	Returned to store all unused bottle. Explained to the letter sender and all worker by briefing about the argon gas usage. Rewarded to the letter sender for sending suggestion letter. Action taken lead by U Tin Aung Swe HSSE Manager	Worker safety awareness increased
15	Land Owner U Mya Thein wants some compensate for his plum trees (4 plum trees are needed to be trim) as it is very close to 6.6 kv string.	U Myint Thein	Hta Naung Tai	Land Owner U Mya Thein wants some compensate for his plum trees (4 plum trees are needed to be trim) as it is very close to 6.6 kv string.	20171109	Than Htun Aung (EPGE), Chan Tha (SDCI) and CRO went down to the village and negotiate with Land Owner for compensation. Land owner U Myint Thein demend two lakh for his 4 trees cutting. The compensation done on 21-11-2017.	U Myint Thein (land owner) agreed and accepted the compensat money MMK200000.
16	Land owner U Phyu send a letter and it's was written that "To Sembcorp Subject: Electric poles installation Regarding to above mentioned subject, I was knew that only three electric pole will be installed in my land and received MMK30,000 and 3 packs of fertilizer bags for three electric pole. But now there are six electric pole was installed in my land and I want MMK30,000 and 3 more fertilizer bags for the additional poles.	U Phyu	Hnan Village	Land owner U Phyu wants compensation money and support fertilizer bags for additional electric poles	20171128	Founded that U Phyu's request is correct. Sembcorp provide MMK30,000 & 2 Fertilizer Bags	on going
17	Head of Link Gyi Village Tract send a letter and decribed as below To Sembcorp, Subject: Recommendation for the land ownership Regarding to above mentioned subject, I am here writing the letter to recommend that the land which Sembcorp installed 3 link bridge concrete pillars is belong to U Nyunt Kyi and informing to make necessary compensation to him. Kind regards, Head of Link Gyi Village Tract 09769629487	U Nyunt Wai	Link Gyi Village	A villager (U Nyunt Wai) who said he is the land owner is asking compensation for his land as Sembcorp install 3 link bridge concrete pillars in his land he said.	20171210	On going - Processing by U Htoon Nay Htoon	on going
18	To Sembcorp, Subject: Land Compensation I can't farm in my land since 2016 as Sembcorp install link bridges in my land and working by workers and vehicle. So, I would like to get compensate money for period of 2016 - 2018. Land Owner U Aung Khin Myint 9/MakhaNa(N)103482	U Aung Khin Myint	Kyun U Village	To Sembcorp, Subject: Land Compensation I can't farm in my land since 2016 as Sembcorp install link bridges in my land and working by workers and vehicle. So, I would like to get compensate money for period of 2016 - 2018. Land Owner U Aung Khin Myint 9/MakhaNa(N)103482	20180123	On going - Processing by U Htoon Nay Htoon	on going
19	09-03-2018 To- Manager, Sembcorp There are 5 concrete poles in 3 places at my Farm and I got only 3 bags of fertilizer bags. Please kindly help me to get balance. U Kyone Taing Hnan Village	U Kyone Tine Lay	Hnan Village	09-03-2018 To- Manager, Sembcorp There are 5 concrete poles in 3 places at my Farm and I got only 3 bags of fertilizer bags. Please kindly help me to get balance. U Kyone Taing Hnan Village	20180309	Check the electric poles on ground with U Kyone Tine. Founded that total 5 poles was installed in U Kyone Tine's farm. As per EPGE and UHNH data, U Kyone received 3 fertilizer bags. Need to pay 2 fertilizer bags more.	Sembcorp provide 2 Fertilizer bags
20	To Sembcorp, Subject: Sending request letter to repair the firm Reference: As per the letter from Daw Mar Mar Ko with the date 2018 March 4 Regarding to the above mentioned subject, I have received a request letter from Daw Mar Mar Ko to get help from Sembcorp to repair her firm (No-138-264/A). Sembcorp Myingyan Company Limited repaired the firms already but Daw Mar Mar Ko's firm left to be repaired. Please kindly support/help to repair her firm as she requested. Nay Soe Oo Administration Officer Hta Naung Tai Village Tract  To Village Tract, Administration Department Date: 2018 March 4 Hta Naung Tai Village, Myingyan Township Subject: Repair firm	U Win Myint Htay (Uncle of Daw Mar Mar Ko)	Hta Naung Tai	To Sembcorp, Subject: Sending request letter to repair the firm Reference: As per the letter from Daw Mar Mar Ko with the date 2018 March 4 Regarding to the above mentioned subject, I have received a request letter from Daw Mar Mar Ko to get help from Sembcorp to repair her firm (No-138-264/A). Sembcorp Myingyan Company Limited repaired the firms already but Daw Mar Mar Ko's firm left to be repaired. Please kindly support/help to repair her firm as she requested. Nay Soe Oo Administration Officer Hta Naung Tai Village Tract  To Village Tract, Administration Department Date: 2018 March 4 Hta Naung Tai Village, Myingyan Township Subject: Repair firm Regarding to above mentioned subject, Sembcorp Myingyan	20180321	Meet with Land owner and explained about the procedure to get the letter from WRUD	on going

## **APPENDIX 6 – COMMUNITY DEVELOPMENT PLAN TABLE OF PROJECTS**

## 2017 - 2018 Construction Period CSR Implementation Plan

Sr.	Township / Village	Venue	Description	Work period	Quotation need to be Provided by procurement	Actual Cost	Remarks
1	Myingyan	Sport and Physical Education Office	Futsal court	12 week			<a href="https://sembcorp-my.sharepoint.com/personal/hein_minoo_sembcorp_com/_layouts/15/guestaccess.aspx?docid=16ff9e2274e66422793ac">https://sembcorp-my.sharepoint.com/personal/hein_minoo_sembcorp_com/_layouts/15/guestaccess.aspx?docid=16ff9e2274e66422793ac</a>
2	Taung Tha	Sport and Physical Education Office	Futsal court	12 week			<a href="https://sembcorp-my.sharepoint.com/personal/hein_minoo_sembcorp_com/_layouts/15/guestaccess.aspx?docid=16ff9e2274e66422793ac">https://sembcorp-my.sharepoint.com/personal/hein_minoo_sembcorp_com/_layouts/15/guestaccess.aspx?docid=16ff9e2274e66422793ac</a>
3	Sarkhaar	Community Hall	Repair roof and bamboo sheet wall (Concrete floor if budget can cover)	2 week			Bamboo Sheet Wall, Galvanized rooftop, Wooden Column, Concrete Floor (Upon to the budget) 40' x 37' , High 11'
	Sarkhaar	School	School Compound Fence 2 side	2 week			'Concrete pole with wiremesh or brick wall (Concrete foundation if budget can cover). Requested by School Principal. Would be changed upon actual cost . Total length 300 x high 5'
	Sarkhaar	School	Classroom - Blackboard (10pcs)	1 week			
	Sarkhaar	School	Toilet (2 room set with one septic tank)	1 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4' , high 7'. One concrete water storage tank (1' x 3' , high 1.5') in each toilet room. One brick water storage tank (4' x 3' , high 3') adjasent to the toilet lengh.
	Sarkhaar	School	10 set of Wooden bench and desk	1 week			(One bench set for 4 student) (10 Set)
	Sarkhaar	Village	Water Treatment system for drinking	1 week			
	Sarkhaar	Village	Stretcher for Ambulance	1 week			Requested by Village Head
4	Hnan	School	Repair classroom	2 week			-Bamboo Sheet Wall, Galvanized rooftop, Wooden Column, bamboo sheet celing, Concrete Floor. 30' x 24' , high 12'
	Hnan	School	Toilet (2 room set with one septic tank)	2 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4' , high 7'. One concrete water storage tank (1' x 3' , high 1.5') in each toilet room. One brick water storage tank (4' x 3' , high 3') adjasent to the toilet lengh.
	Hnan	Village	Water Treatment system for drinking	1 week			
5	Phet Taw	School	10KVA Step up Transformer	1 week			Strongly requested by School Principal and VH
	Phet Taw	School	Classroom - Repair roof and building (Concrete floor if budget can cover)	2 week			'-Bamboo Sheet Wall, Galvanized rooftop, Wooden Column, bamboo sheet celing, Concrete Floor if budget can cover. 60' x 24' , high 15'
	Phet Taw	School	20 pcs Whiteboard (8' X 4') & 20 box of whiteboard markers pen	1 week			
	Phet Taw	School	80 set of Wooden bench and desk	1 week			(One bench set for 4 student) (80 Set)

## 2017 - 2018 Construction Period CSR Implementation Plan

Sr.	Township / Village	Venue	Description	Work period	Quotation need to be Provided by procurement	Actual Cost	Remarks
	Phet Taw	School	2 Toilet Building (2 room set with one septic tank)	1 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4' , high 7'. One concrete water storage tank (1' x 3' , high 1.5') in each toilet room. One brick water storage tank (4' x 3' , high 3') adjasent to the toilet lengh.
	Phet Taw	School	Repair the existing Water Treatment system for drinking	1 week			Requested by School Principal
	Phet Taw	Village	Water Treatment system for drinking	1 week			
6	Nyaung Kan	School	Teacher quarter	2 week			"-Bamboo Sheet Wall, Galvanized rooftop, Wooden Column, bamboo sheet celing, Concrete Floor. 30' x 20' , high 10'
	Nyaung Kan	School	10 pcs Whiteboard (8' X 4') & 10 box of whiteboard markers pen	1 week			
	Nyaung Kan	School	20 set of Wooden bench and desk	1 week			(One bench set for 4 student) (20 Set)
	Nyaung Kan	School	Repair Toilet wall (No Need the tank), 2 Toilet. On existiing septic tank	1 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4' , high 7'. One concrete water storage tank (1' x 3' , high 1.5') in each toilet room. One brick water storage tank (4' x 3' , high 3') adjasent to the toilet lengh.
	Nyaung Kan	School	Repair Kitchen	1 week			3' high brick wall and 5' iron squar mesh, Concrete floor, 8' x 8'. Steel Structure (for Teacher)
	Nyaung Kan	Village	Water Treatment system for drinking	1 week			
7	Thein	School	2 pcs Whiteboard (8' X 4') & 2 box of whiteboard markers pen	1 week			
	Thein	School	10 set of Wooden bench and desk	1 week			(One bench set for 4 student) (10 Set)
	Thein	School	Toilet (2 room set with one septic tank)	2 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4' , high 7'. One concrete water storage tank (1' x 3' , high 1.5') in each toilet room. One brick water storage tank (4' x 3' , high 3') adjasent to the toilet lengh.
	Thein	Village	Water Treatment system for drinking	1 week			need generator for power supply.
	Thein	Village	Steel structure building	1 week			8' X 10', high high 8'. Concrete floor with iron square mesh with steel structure to place water treatment system and existing water pump
	Gyoke Pin	School	School compound fence,for 2 side (the rest 2 sides already covered with brick wall)	2 week			"Concrete pole with wiremesh or brick wall (Concrete foundation if budget can cover). Requested by School Principal. Would be changed upon actual cost . Total lengh 400 x high 5'
	Gyoke Pin	School	4 pcs Whiteboard (8' X 4') & 4 box of whiteboard markers pen	1 week			

## 2017 - 2018 Construction Period CSR Implementation Plan

Sr.	Township / Village	Venue	Description	Work period	Quotation need to be Provided by procurement	Actual Cost	Remarks
8	Gyoke Pin	School	40 set of Wooden bench and desk	1 week			(One bench set for 4 student) (40 Set)
	Gyoke Pin	School	Toilets (2 rooms with one septic tank)	2 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4', high 7'. One concrete water storage tank (1' x 3', high 1.5') in each toilet room. One brick water storage tank (4' x 3', high 3') adjasent to the toilet lengh.
	Gyoke Pin	Village	Water Treatment system for drinking	1 week			
	Gyoke Pin	Village	Road repairing for partial ( they have some government budget already, but still need some more as 4,000,000MMK to complete it)	-			Road (250' x 20' x 6"), Road upgrading will be costed at MMK10,000,000. Government support MMK4,500,000 and village inhand funs MMK1,500,000. The village requested (Cash Donation) from Sembcorp for the shortage MMK4,000,000. Strongly requested by Village Head during Public Stakeholer Engagement
9	Hta Naung Tai	School	10 pcs Whiteboard (8' X 4') & 10 box of whiteboard markers pen	1 week			
	Hta Naung Tai	School	130 set of Wooden bench and desk	1 week			One bench set of 4 student (130 set). Requested by school principal
	Hta Naung Tai	School	Toilet (2 rooms with one septic tank)	2 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4', high 7'. One concrete water storage tank (1' x 3', high 1.5') in each toilet room. One brick water storage tank (4' x 3', high 3') adjasent to the toilet lengh.
	Hta Naung Tai	Village	Water Treatment system for drinking (2 set)	1 week			
10	Aye	School	Build Kitchen	1 week			'3' high brick wall and 5' iron squaremesh, Concrete floor, 8' x 8'. Steel Structure (for Teacher)
	Aye	School	Concrete foundation, concrete pole and wiremesh for school compound fence. Need iron Door with frame for entrance.	2 week			Total lengh 540' x 5' high.Requested by School Principal
	Aye	School	Compressor with diesel engine for existing well. Support set for drinking water area (to place PH7 bottle and cups.)	1 week			Requested by School Principal
	Aye	School	3 pcs Whiteboard (8' X 4') & 3 box of whiteboard markers pen	1 week			
	Aye	Village	Water Treatment system for drinking	1 week			Need generator for power supply
11	Ma Yoe Kone	School	3 pcs Whiteboard (8' X 4') & 3 box of whiteboard markers pen	1 week			
	Ma Yoe Kone	School	Concrete building for existing water pump with diesel engine. (3' concrete foundation (to avoid flooding time), 6' x 6', 4'high wall with iron squaremesh)	1 week			Requested by School Principal

## 2017 - 2018 Construction Period CSR Implementation Plan

Sr.	Township / Village	Venue	Description	Work period	Quotation need to be Provided by procurement	Actual Cost	Remarks
	Ma Yoe Kone	School	New ceiling for Teacher quarter. 10' X 16' with bamboo sheet	1 week			Requested by School Principal
	Ma Yoe Kone	Village	Water Treatment system for drinking	1 week			Need generator for power supply
12	Tha Pyay Thar	School	Classroom - Repair ceiling and brick wall (Concrete floor if budget can cover)	2 week			brick wall, Ceiling. 56' x 30', high 10'
	Tha Pyay Thar	School	Toilet (2 room set with one septic tank)	2 week			Concret Floor, Brick Wall and Galvanized rooftop. 8' x 4', high 7'. One concrete water storage tank (1' x 3', high 1.5') in each toilet room. One brick water storage tank (4' x 3', high 3') adjacent to the toilet length.
	Tha Pyay Thar	Village	Water Treatment system for drinking	1 week			Need generator for power supply
13	Sate Nyan	School	10 set of Wooden bench and desk	1 week			(One bench set for 4 student) (10 Set)
	Sate Nyan	School	H4' x L30', brick wall for existing classroom. Some part already cover with brick wall	2 week			
	Sate Nyan	Village	Water Treatment system for drinking	1 week			Need generator for power supply
14	Ka Lain Chone	School	Classroom -only need to renovate with brick wall	2 week			Roof, ceiling and concrete floor are existing. 25' x 15', high 15'
	Ka Lain Chone	School	15 set of Wooden bench and desk	1 week			(One bench set for 4 student) (15 Set)
	Ka Lain Chone	Village	Water Treatment system for drinking	1 week			Need generator for power supply
15	Kyun U	School	Classroom repair - Bamboo sheet wall (Ground floor)	2 week			Requested by School Principal. 57' x 17', High 8'
	Kyun U	School	Repair bench and chair (12 set)	1 week			
	Kyun U	School	School Compound Fence 2 side	2 week			Concrete pole with wiremesh or brick wall (Concrete foundation if budget can cover). Requested by School Principal. Would be changed upon actual cost . Total length 600' x high 5'
	Kyun U	Village	Water Treatment system for drinking	1 week			Need generator for power supply



**APPENDIX 7 – LIST OF POWER POLES AND FERTILIZER BAGS  
PROVIDED PER PAP**

No	District	Village	NRC	Plot	No. Fertilizer Bags
1	Mingyan	Sa Khar	9/TaThaNa(N)013175	278-Ka	3
2	Mingyan	Sa Khar	9/TaThaNa(N)014670	278-Ka	2
3	Mingyan	Sa Khar	9/MaKhaNa(N)022294	278-Ka	3
4	Mingyan	Sa Khar	9/MaKhaNa(N)022294	278-Ka	4
5	Mingyan	Sa Khar	9/MaKhaNa(N)089999	278-Ka	4
6	Mingyan	Gyoke Pin	9/MaKhaNa(N)124563	283	3
7	Mingyan	Gyoke Pin	9/TaThaNa(N)013695	283	3
8	Mingyan	Gyoke Pin	9/MaKhaNa(N)106259	283	2
9	Mingyan	Gyoke Pin	9/MaKhaNa(N)105852	283	3
10	Mingyan	Gyoke Pin	9/MaKhaNa(N)133847	283	2
11	Mingyan	Gyoke Pin	9/TaThaNa(N)056181	283	6
12	Mingyan	Gyoke Pin	9/MaKhaNa(N)171281	283	1
13	Mingyan	Gyoke Pin	9/TaThaNa(N)096180	283	2
14	Mingyan	Gyoke Pin	9/TaThaNa(N)055491	283	2
15	Mingyan	Gyoke Pin	9/MaKhaNa(N)106522	283	1
16	Mingyan	Gyoke Pin	9/TaThaNa(N)096180	283	1
17	Mingyan	Gyoke Pin	9/TaThaNa(N)0161596	283	3
18	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)123474	264-Kha	3
19	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)187967	264-Kha	1
20	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)157658	264-Kha	2
21	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)059613	264-Kha	2
22	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)066468	264-Kha	5
23	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)059653	264-Kha	3
24	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)057488	264-Ka	1
25	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)060068	264-Ka	3
26	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)066468	264-Ka	6
27	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)121452	264-Ka	7
28	Mingyan	Hta Nyaung Thai	9/TaThaNa(N)224565	264-Ka	4
29	Mingyan	Hta Nyaung Thai	9/MaKhaNa(N)289757	264-Ka	5

No	District	Village	NRC	Plot	No. Fertilizer Bags
30	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)056957	264-Ka	2
31	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)170715	264-Ka	5
32	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)235048	264-Ka	2
33	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)057048	264-Ka	3
34	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)001777	264-Ka	4
35	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)057089	264-Ka	4
36	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)029615	263	8
37	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)083548	263	1
38	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)059758	263	1
39	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)061121	263	3
40	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)060824	263	1
41	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)060623	263	3
42	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)153788	263	1
43	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)061150	263	2
44	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)060951	263	2
45	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)060623	262	3
46	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)103482	262	6
47	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)103679	262	1
48	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)104002	262	5
49	Myingyan	Hta Nyaung Thai	9/TaThaNa(N)053955	262	3
50	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)103822	262	1
51	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)101833	262	1
52	Myingyan	Hta Nyaung Thai	9/TaThaNa(N)013358	262	2
53	Myingyan	Hta Nyaung Thai	9/TaThaNa(N)013358	262	1
54	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)057463	262	5
55	Myingyan	Lint Gyi	9/MaKhaNa(N)104762	260	1
56	Myingyan	Lint Gyi	9/MaKhaNa(N)104838	260	3
57	Myingyan	Lint Gyi	9/MaKhaNa(N)001658	260	3
58	Myingyan	Lint Gyi	9/TaThaNa(N)086365	260	4

No	District	Village	NRC	Plot	No. Fertilizer Bags
59	Myingyan	Lint Gyi	9/MaKhaNa(N)103510	260	1
60	Myingyan	Lint Gyi	9/MaKhaNa(N)103487	260	1
61	Myingyan	Lint Gyi	9/MaKhaNa(N)104760	260	2
62	Myingyan	Lint Gyi	9/MaKhaNa(N)104371	260	6
63	Myingyan	Lint Gyi	9/MaKhaNa(N)104731	258-Ka	4
64	Myingyan	Lint Gyi	9/MaKhaNa(N)104630	258-Ka	2
65	Myingyan	Lint Gyi	9/MaKhaNa(N)001792	258-Ka	2
66	Myingyan	Lint Gyi	9/MaKhaNa(N)104630	258-Ka	4
67	Myingyan	Lint Gyi	9/MaKhaNa(N)104595	258-Ka	1
68	Myingyan	Lint Gyi	MGN-217535	258-Ka	2
69	Myingyan	Lint Gyi	9/MaKhaNa(N)104591	258-Ka	2
70	Myingyan	Gyoke Pin	9/MaKhaNa(N)151151		7
71	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)059871		5
72	Myingyan	Hta Nyaung Thai	9/MaKhaNa(N)059817		3
73	Myingyan	Hta Nyaung Thai			3
74	Myingyan	Hta Nyaung Thai			4
75	Myingyan	Hta Nyaung Thai			1
76	Myingyan	Hta Nyaung Thai			2
77	Myingyan	Hta Nyaung Thai			3
78	Myingyan	Hta Nyaung Thai			1
79	Myingyan	Hta Nyaung Thai	betel leaf		1
1	Taungtha	Nyaung Kan	9/TaThaNa(N)055465	933	2
2	Taungtha	Nyaung Kan	9/TaThaNa(N)112917	933	4
3	Taungtha	Nyaung Kan	9/TaThaNa(N)082687	933	1
4	Taungtha	Nyaung Kan	9/TaThaNa(N)056298	933	1
5	Taungtha	Nyaung Kan	9/TaThaNa(N)055448	933	1
6	Taungtha	Hta Nyaung Thai	9/TaThaNa(N)022163	932	2
7	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)243933	932	7

No	District	Village	NRC	Plot	No. Fertilizer Bags
8	Taungtha	Nyaung Kan	8/YaSaKa(N)118977	932	1
9	Taungtha	Nyaung Kan	9/TaThaNa(N)096202	932	4
10	Taungtha	Nyaung Kan	9/TaThaNa(N)055447	932	2
11	Taungtha	Nyaung Kan	9/MaKhaNa(N)059479	932	4
12	Taungtha	Nyaung Kan	9/TaThaNa(N)056222	932	3
13	Taungtha	Nyaung Kan	9/TaThaNa(N)055409	932	7
14	Taungtha	Nyaung Kan	9/TaThaNa(N)055409	932	3
15	Taungtha	Nyaung Kan	9/TaThaNa(N)055461	932	8
16	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)057763	932	5
17	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)154044	932	4
18	Taungtha	Ywar Tha Gone	9/MaKhaNa(N)057824	932-Ka	5
19	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)056918	932-Ka	4
20	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)057715	932-Ka	2
21	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)057493	932-Ka	3
22	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)189971	932-Ka	4
23	Taungtha	Ywar Tha Gone	9/MaYaTa(N)103111	932-Ka	5
24	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)104762	932-Ka	4
25	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)056941	932-Ka	4
26	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)056819	932-Ka	2
27	Taungtha	Ywar Tha Gone	9/MaKhaNa(N)057827	932-Ka	10
28	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)056895	932-Ka	2
29	Taungtha	Ywar Tha Gone	9/MaKhaNa(N)059659	932-Ka	1
30	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)057774	932-Ka	4
31	Taungtha	Hta Nyaung Thai	9/MaKhaNa(N)096640	932-Ka	3
32	Taungtha	Aye	9/TaThaNa(N)086365	797	3
33	Taungtha	Aye	9/TaThaNa(N)053830	797	2
34	Taungtha	Aye	9/MaKhaNa(N)071189	797	1
35	Taungtha	Aye	9/TaThaNa(N)053840	797	3
36	Taungtha	Aye	9/TaThaNa(N)053974	797	1

No	District	Village	NRC	Plot	No. Fertilizer Bags
37	Taungtha	Kyun U	9/TaThaNa(N)153806	797	5
38	Taungtha	Aye	9/TaThaNa(N)090080	797	1

District	AP	Fertilizer Bags
Myingyan	79	225
Taungtha	38	128
Total	117	353

Please note: while NRC and plot numbers are missing from this table for a few PAPs, the identity of these PAPs is known and ENVIRON has been provided with their names, but the names have been omitted from this table for confidentiality purposes.